



1



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 24 th floor; looking east and up; showing water staining	↑

2



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 24 th floor; looking southeast and down; showing water staining	↑



3



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 23 rd floor; looking east and up; showing water staining	↑

4



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 23 rd floor; looking east; showing water staining	↑



5



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 23 rd floor; looking south and up; showing water staining	↑

6



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 22 nd floor; looking southwest; showing water staining and suspect fungal growth	↑



7



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 22 nd floor; looking southwest and up; showing water staining	↑

8



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 21 st floor; looking southwest; showing suspect fungal growth	↑



9



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 20 th floor; looking southwest; showing suspect fungal growth	↑

10



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 20 th floor; looking southwest; showing suspect fungal growth	↑



11



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 19 th floor; looking southwest; showing suspect fungal growth	↑

12



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 19 th floor; looking south; showing suspect fungal growth	↑



13



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 18 th floor; looking southwest and down; showing suspect fungal growth	↑

14



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 18 th floor; looking south and down; showing suspect fungal growth	↑



15



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 17 th floor; looking southeast and up; showing water staining	↑

16



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 16 th floor; looking southwest; showing suspect fungal growth	↑



17



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 16 th floor; looking south; showing suspect fungal growth	↑

18



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 15 th floor; looking south; showing suspect fungal growth	↑



19



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 13 th floor; looking south and up; showing water staining	↑

20



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 13 th floor; looking southwest and up; showing water staining	↑



21



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 11 th floor; looking northwest and up; showing water staining	↑

22



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 11 th floor; looking northwest; showing water staining	↑



23



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 11 th floor; looking southwest; showing water staining and rust	↑

24



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 11 th floor; looking south and up; showing water staining	↑



25



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 10 th floor; looking west and up; showing water staining	↑

26



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 10 th floor; looking west; showing water staining	↑



27



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 9 th floor; looking west; showing water staining	↑

28



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 8 th floor; looking south and up; showing water staining	↑




29



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 5 th floor; looking west; showing water staining	↑

30



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 5 th floor; looking west and up; showing water staining	↑



31



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 4 th floor; looking west and up; showing water staining	↑

32



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 4 th floor; looking southwest and up; showing water staining	↑



33



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; 2 nd floor; looking south; showing water staining	↑

34



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; pit; looking east and down; showing efflorescence and water staining on concrete elevator pit surfaces	↑



35



Date	Address	Photo Location – Description	Up
08/17/08	450 N Street Sacramento, California	Elevator Shaft 6; pit; looking east and down; showing efflorescence and water staining on concrete elevator pit surfaces	↑